

US EPA ARCHIVE DOCUMENT

# Situation Photo Log

Wednesday, October 24, 2012

Kalamazoo River / Enbridge Spill

## Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C0.4 Boat Launch Gauge	57.33	56.85
Ceresco Dam Control Point Boom	56.95	56.37
E4 Boat Launch Gauge	62.83	59.08

Prepared by:  
Matthew Haak  
START-USEPA  
Situation Unit



1. MP5.25 LDB area where sheen and tar globs were observed.



2. MP5.35 LDB sheen and tar globs observed.



3. MP5.45 LDB sheen and tar globs observed.



4. MP5.63 LDB sheen and tar globs observed.



5. MP5.63 LDB sheen and tar globs observed.



6. Ceresco Dam Control Point Boom.





**7. Ceresco Dam Control Point Boom observed sheen and tar globs collecting along the boom.**



**8. MP5.63 RDB sheen and tar globs observed.**



9. MP5.55 RDB sheen observed.



10. MP5.15 RDB sheen observed.



11. MP5.15 RDB sheen observed.



12. Morrow Lake Delta Gate E observed crews inspecting containment curtain.





13. Morrow Lake observed a poling crew.



14. Morrow Lake observed a poling crew.



15. Morrow Lake south cove sheen observed.



16. Morrow Lake south cove sheen observed.





**17. Morrow Lake Delta Gate F sheen observed along the boom.**



**18. MP36.5 observed a hunter exiting the wetland area.**